

FIELD INSPECTION REPORT

Date of Inspection :	5.12.2020	District:	Punha
Division :	BAISI	Length (km):	4.970 KM
Name of the Road:	Dhasambari to chilhani		
Scheme/Programme:	MAINTENANCE		
Package No.:	MR. N/2019-20 Baisi/21	Road Id No.:	
Status of the Project:	☒ Ongoing/Completed/Under Maintenance		
Work is a case of:	☒ New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ SAI
b)	Condition of Surfacing	✓ SAI
c)	Riding Quality	✓ SAI
d)	Road Camber	✓ SAI
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S SRI NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI NA
c)	Condition of railings/slab/approach for Bridges	S SRI NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	Yes/No NA
4.	Compliance History	
a)	Status of ATR's & any others	WORK in Progress

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)


 (Signature)
 A.E. Baisa

NAME:
 Asim Kumar