

FIELD INSPECTION REPORT

Date of Inspection :	6.12.2020	District:	Purnea
Division :	Baisa	Length (km):	3.280 KM
Name of the Road:	Approach road to Chandaul		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance ☒		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ☒		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓/U
b)	Condition of Surfacing	✓/U
c)	Riding Quality	✓/U
d)	Road Camber	✓/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/ NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/ NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :


Except damage in flood.

Satisfactory (S)

"S"

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)


6/12/2020
(Signature)

NAME:
Asim Kumar

A. E. Baisa