FIELD INSPECTION REPORT

Date of Inspection:	7-12-2020	District: Saran
Division: ROD(W) DIV' Chapmen		Length (km): 2.730
Name of the Road:	sampure to	Patolina
Scheme/Programme:	MAINTENANCE	
Package No.: me-N /	10-22 Chapsen 12	Road Id No.:
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	
c)	Riding Quality	
d)	Road Camber	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	
f)	Contraction Joints provided or not (CC Pavement)	
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	Land San S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	I AND THE PRODUCT

Tendor not decidal

(Signature)

NAME:

DESIGNATION:

JE Lallador