FIELD INSPECTION REPORT		
Date of Inspection: 5/13/20		
Division: Madagas		
Name of the Road: PMD road to Rangusta Scheme/Programme: MADITINANON		
Scheme/Programme: MAINTENANCE		
Package No.:mk-N/19-20 Mckaygey H Royd Id No		
Ongoing Completed Inder Maintenant		
Work is	a case of: New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement BT not Strated	100
a)	Road Junction condition	S/U
b)	N/A	S/U
c)	Piding Quelit	S/U
d)	N//1	
	N/A	S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	Cross Drainage	1 370
(a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
1.	Compliance History	
a)	Status of ATR's & any others pot refair & flank fitting work poro Porting: [a ii fortow: (5)]	alo any
Overall		2 5 8
Catisfactory but requires Improvement (Car		

Unsatisfactory (U)

Ram Sagor Das

(Signature)