FIELD INSPECTION REPORT

Status	ge No. RM/NA/BEN/19/08Road Id No.: 3/910001 of the Project Ongoing Completed Under Maintenance is a case of: New Connectivity Up gradation Maintenance	027
	William to be sheeted	Remarks
SI. No.		
L	Pavement	8/0
223	Road Junction condition	S/U
53	Condition of Surfacing	S/U
S.F.	Riding Quality	570
di e)	Road Camber Whether free from defects such as visible cracks, exposed accregates in case of CC Pavement.	Yes/No
15	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank-slope & mincuts if any	Yes/No
2.	Cross Drainage	
(8)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
ы	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
ey:	Condition of railings/slab/approach for Bridges	S/SRI/U
3,	Road Furniture	
0	Whether sign boards informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
0	Status of ATR's & any others	1

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NOTE O WOrk is pending

NAME: Madan chardhay

DESIGNATION: J. E.