## FIELD INSPECTION REPORT

Scheme Package Status o	Programme:	Dally Length (km) 2 530 KI a) To Hakus  MBEN/19/6 Road to No. 2/9/0002  Togother completed to the Management completed to the Management of the Management o	672
St. No.	Parameters to be checked		Remarks
10	Pavement		
. (4)	Rond Janeton soudition		907.7
753	Condition of Statisting		
:03	Riding Quality		9/1)
66	Road Camber		5(4)
65	Whether free from defects such as visible cracks, expected aggregates in case of CC Pavement.		Yes/No Yes/No Yes/No Yes/No S/SRI/U S/SRI/U
.ń	Contraction Joints provided or not (CC Pavement)		YevNo
905	Compaction of flank/slope & raincuts if any		YevNo
2.	Cross Drains	nge .	
85	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
6)	Condition of milings/slab approach for Bridges		S/SRI/U
3,	Road Furnit	niture	
aï	Whether sign boards informatory/cautionary Board km & 200m shones Pavement road markings are provided and maintained		m Yes/No
4.	Compliance History		
ii)	Status of AT	C's & any others	

Overall Rating

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

NOTED Site clearing is progress

(I) Pot patch & SDBC work ispending

(Signature)

NAME: Madem chardhay
DESIGNATION: J. E.