FIELD INSPECTION REPORT

| Date of Inspection: 07.12.2020 | | District: Machebeni | |
|--------------------------------|--|---------------------------|--|
| Division: R.W.D(| w Myholpsosh. | Length (km): 2.22 0 Km | |
| Name of the Road: 1/4 | hutaung to | Baradhant | |
| Scheme/Programme: | MAINTENANCE | | |
| Package No.: | 1/ | Road Id No .: 31909900824 | |
| Status of the Project: | Road Id No.: 31909900824 Ongoing/Completed/Under Maintenance | | |
| Work is a case of: | New Connectivity/Up gradation/ Maintenance | | |

| Sl. No. | Parameters to be checked | Remarks |
|----------------|--|---------|
| 1. | Pavement | |
| a) | Road Junction condition | /S/U |
| b) | Condition of Surfacing | ~870 |
| c) | Riding Quality | r S/U |
| d) | Road Camber | VS/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | |
| f) | Contraction Joints provided or not (CC Pavement) No Pcc Pavement | Yes/No |
| g) | Compaction of flank/slope & raincuts if any | Wes/No |
| 2. | Cross Drainage | |
| | The place of the state of the s | S/SRI/U |
| a) | Condition of head walls in Hume pipe culverts including its painting | SISINIO |
| a) b) | Condition of head walls in Hume pipe culverts including its painting Condition of Abutment & Wing walls, Slab in RCC culverts | S/SRI/U |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | |
| b) c) | | S/SRI/U |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges | S/SRI/U |
| b) c) 3. | Condition of Abutment & Wing walls, Slab in RCC culverts Condition of railings/slab/approach for Bridges Road Furniture Whether sign boards/informatory/cautionary Board/km & 200m | S/SRI/U |

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

(Signature)7-12-201

NAME: JITENDRA KUMAL

DESIGNATION: 4E