Inspection of Roads Under MR (3054) In Chausa Block

FIELD INSPECTION REPORT

| ate of Inspection: 03,12, 3,220 | | | District: Buxax | |
|---------------------------------|--|--------------------|----------------------------|-------------------|
| 1 | | | Length (km): 2.00 | |
| ame of | the Road: Buch | er-Sasaram PWD | Road to Khilaphathur Under | "IK (SOUT) INCO |
| cheme/F | rogramme: | MAINTENANCE | Road Id No.: | |
| ackage | | ViCampleted | /Under Maintenance | |
| | the Project: | New Connectivity/U | Jp gradation/ Maintenance | |
| | | Parameters to | | Remarks |
| 1. | Pavement | | | |
| | Road Junction condition | | | Š/U |
| a) | | | | Š/U |
| b) | Condition of Surfacing | | | S/U |
| c) | Riding Quality | | | S /U |
| d) | Road Camber Whether free from defects such as visible cracks, exposed | | | Yes/No |
| e) | aggregates in case of CC Pavement. | | | Yes/No |
| f) | Contraction Joints provided or not (CC Pavement) | | | Yes/No |
| g) | Compaction of flank/slope & raincuts if any | | | Yes/No |
| 2. | Cross Drain | | | / |
| a) | Condition of head walls in Hume pipe culverts including its painting | | | š/SRI/U |
| b) | Condition of Abutment & Wing walls, Slab in RCC culverts | | | -S/SRI/U |
| c) | Condition of railings/slab/approach for Bridges | | | -S/SRI/U |
| 3. | Road Furniture | | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | | Yes/No |
| 4. | Compliance History | | | The second second |
| a) | Status of ATR's & any others | | | No. |

Overall Rating

| Satisfactory (S) | `S' |
|---|-----|
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

Monado 3:12.20%

NAME: Maya Ward brosed

DESIGNATION: J.E.