

Inspection of Roads Under MR (3054) in Chausa Block

FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020		District: Buxar	
Division : Buxar		Length (km): 1.400	
Name of the Road: Chausa - Station Road to Kishnapuri Under MR (3054) New Policy			
Scheme/Programme:		MAINTENANCE	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No N.A.
g)	Compaction of flank/slope & raincuts if any		Yes/No N.A.
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U N.A.
c)	Condition of railings/slab/approach for Bridges		S/SRI/U N.A.
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No N.A.
4.	Compliance History		
a)	Status of ATR's & any others		No.

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

M. Basud
(Signature) 03.12.2020

NAME: Maya Nand Basud

DESIGNATION: J.E.