## FIELD INSPECTION REPORT

Date of Inspection :	2.12.2020	District: Samaslibus	
Division: Scenarti four		Length (km): 2.084 K· M	
Name of the Road: Lo	029 - TOG TO	Kuste Ahar (VR29)	
Scheme/Programme:			
Package No.: BR	- 30R-460	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

The Confectivity of graduiton intermed			
Sl. No.	Parameters to be checked	Remark	
1.	Pavement		
a)	Road Junction condition	YS/U	
b)	Condition of Surfacing	√8/U	
c)	Riding Quality	~8/U	
d)	Road Camber	~8/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/Nø	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	~Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/Ø	
c)	Condition of railings/slab/approach for Bridges	S/S/RI/U	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	NO	

Overall Rating

Satisfactory (S)	0
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Shashi Bhushau Ry
NAME: