FIELD INSPECTION REPORT

Date of I	nspection: o	7/12/20	District: SIW:	O N
1016141	MAHO	OTG NIT	Length (km):	4 14
Name of	the Road: 🛺	ACCUANDUR		
Scheme/	rrogramme:	MAINTENANCE	HAST MAHAMADPUR	TO BAH
Package			Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance IN TEND		TENDE
Work is	a case of:	New Connectivity/U	Jp gradation/ Maintenance	101,40
Sl. No.		Parameters to		Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)	Status of ATR's & any others			NO

Overall Rating

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

(Signature)

NAME:

DESIGNATION:

MANISH KUMAR OTHA
(J.G.)

N/A