## FIELD INSPECTION REPORT

Dat	e of Inspection: 08.12.20 District: East Charpe	ga	
Div	Division: Paral Length (km): 30 Kg		
Nan	re of the Road: Blelan to Puranda (629)	and the second s	
	eme/Programme: [MAINTENANCE 3034]		
Pacl	Road Id No.: 31768508	040	
-	as of the Project: Ongoing/Completed/Under Maintenance	The second second	
Wor	k is a case of: New Connectivity/Up gradation/ Maintenance	Remark	
SI. N	Ro. Parameters to be checked	Remark	
1.	Pavement		
(1)	Road Junction condition	\S/U	
b)	Condition of Surfacing	15/11	
c)	Riding Quality	S/U	
d)	Road Camber	<b>/8/U</b>	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Xcs/No	
1)	Contraction Joints provided or not (CC Pavement)	Xes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	/S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	√S/SRI/U	
:)	Condition of railings/slub/approach for Bridges	∕\$/SRI/U	
3.	Road Furniture		
)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	√Y'es/No	
,	Compliance History		
	Status of ATR's & any others	NA	

Overall Rating

Satisfactory (S)	(5)
Satisfactory but requires Improvement (S)	RI)
Unsatisfactory (U)	

(Signature)

NAME: Milled Komerais DESIGNATION: Ourior Eiginer, Remais