

# FIELD INSPECTION REPORT

Date of Inspection : 10-12-2020		District: Dambhanga	
Division : Dambhanga-1		Length (km): 1.140 km	
Name of the Road: Tola to Nandania Bahadur			
Scheme/Programme: MAINTENANCE		Road Id No.:	
Package No.:		Ongoing/Completed/Under Maintenance	
Status of the Project:		New Connectivity/Up gradation/ Maintenance	
Work is a case of:		Parameters to be checked	
Sl. No.		Remarks	
<b>1. Pavement</b>			
a)	Road Junction condition	S/U	✓
b)	Condition of Surfacing	S/U	✓
c)	Riding Quality	S/U	✓
d)	Road Camber	S/U	✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No	Yes
<b>2. Cross Drainage</b>			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/U	SR
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/U	✓
c)	Condition of railings/slab/approach for Bridges	S/SR/U	
<b>3. Road Furniture</b>			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	No
<b>4. Compliance History</b>			
a)	Status of ATR's & any others	No.	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Note:- Road damaged in flood. Temporary restoration done. Permanent restoration to be started. DPR preparation work in progress.

*[Signature]*

NAME:

(Signature)

DESIGNATION: