FIELD INSPECTION REPORT

17,13,		LIEFD INSECTION	REPURI	
Date	of Inspection:	10/12/2020	District:	Darbhange
Division:		Donablange - 1	Length(Km):	Darbharge 0.140
Name of Road:		Desharge - 1 Novtoli to Toz	To Navto	
Scheme/Progrmme:		Maintenance		
Package No.			Road Id No.	
Status of the Project:		Ongoing/Completed/ Under Maintenance		
Work is a case of:		New Connectivity/Up gradation/ Maintenance		
		rameters to be Checcked		
				Remarks
1	Pavement			
<u>a)</u>	Road Junction condition			S/U _C
<u>p)</u> .	Condition of Surfacing			S/U s
<u>c)</u>	Riding Quality			S/U _
d)				S/U -
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No アラ
g)	Compaction of flank /slope & raincuts if any		Yes/No No	
2	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			ለ/ል S/SRI/U
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts			KAA S/SRI/U
c)_	Condition of railing /slabs/ approach for Bridges			S/SRI/U4/4
3	Road Furniture			
	Whethersign boards/informatory/cautionary Board/Km & 200m stones/Pavement road markings are provided and maintained		Yes/No	
3	Complianace History			
a)	Status of ATR's & any others			No
9				
veral	l Rating:			
	<u> </u>	Satisfactory (S)		
	<u>-</u>	Satisfactory but requires Impi	rovement (SRI)	COL
	I	Insatisfactory (U)	13.	

Name:

Designation:

(Signature)