A

## FIELD INSPECTION REPORT

Date of Inspection: 03.12.20 20 District: **Division:** Length (km): 5.00 KM Banka 2

Name of the Road: Asom phermshala More (Katoriachendan RCDR) to Dhaboni

Scheme/Programme: **MAINTENANCE** 

Package No.: Road Id No.:

Status of the Project: Ongoing/Completed/Under Maintenance

Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	Š/U
b)	Condition of Surfacing	Š/U
c)	Riding Quality	Š/U
d)	Road Camber	š/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement Bituminus Road	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	MA

Overall Rating

Satisfactory (S)	
	7
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	

(Signature)

NAME: Yogeshwar Pandey

DESIGNATION: chief Engineer 2