FIELD INSPECTION REPORT

		FIELD INSTI	X.1.0	
	19.	Tulana	District: Purnea	
Date of Inspection: 10 / 12/2020			Length (km): 3.450	
Division	: Basi	- la Man	un la Ye	
Name of	the Road: CH	MAINTENANCE	(MX 3054)	
	Programme:		Road Id No.:	
Package	No.:	Ongoing/Complete	ed/Under Maintenance	
Status of the Project: Ongoing/Complet Work is a case of: New Connectivity		New Connectivity	/Up gradation/ Maintenance	
	a case on	Parameters (to be checked	Remarks
Sl. No.				
1.	Pavement			SIUNA
a)	Road Junction condition			S/U NA
b)	Condition of Surfacing			
c)	Riding Quality			S/U HA
d)	Road Camber			S/U HA
 c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No NA
	Contraction Joints provided or not (CC Pavement)			Yes/No HA
U)	Compaction of flank/slope & raincuts if any			Yes/No H
g)				
2.	Cross Drainage Condition of head walls in Hume pipe culverts including its painting S/SRI/U			
a)	Condition of field waits in trains pro-			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U P
c)	Condition of railings/slab/approach for Bridges			S/SRI/U H
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)	Status of ATR's & any others			110

Overall Rating

Satisfactory (S)	-MA- (Reconfly wo
Satisfactory but requires Improvement (SRI)	had been started
Unsatisfactory (U)	

NAME: GLAURAV KUMAR

DESIGNATION: ASSISTANT EMAINTER