FIELD INSPECTION REPORT

Oate of Inspection: 09.12.2020 Distrcit: SARAN

Division: SONPUR Length (km):3.900

Name of the Road: Bankerwa Bhaw Se Kuari Azam

Scheme/Programme: MAINTENANCE

Package No: Road ID No:

Status of The Project: ONGOING

		,	0,100,110
Work is a	case of	: Ma	intenance

a) Road Junction Condition b) Condition of Surfacing c) Riding Quality d) Road Camber e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. f) Contraction Joints provided or not (CC Pavement) g) Compaction of Flank/slope & raincuts if any 2 Cross Drainage Condition of head walls in Hume pipe Culverts including its painting	\$ \$ \$ \$
b) Condition of Surfacing c) Riding Quality d) Road Camber Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. f) Contraction Joints provided or not (CC Pavement) g) Compaction of Flank/slope & raincuts if any Cross Drainage Condition of head walls in Hume pipe Culverts including its painting	\$ \$ \$
c) Riding Quality d) Road Camber e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. f) Contraction Joints provided or not (CC Pavement) g) Compaction of Flank/slope & raincuts if any 2 Cross Drainage Condition of head walls in Hume pipe Culverts including its painting	S S
d) Road Camber Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. f) Contraction Joints provided or not (CC Pavement) g) Compaction of Flank/slope & raincuts if any 2 Cross Drainage Condition of head walls in Hume pipe Culverts including its painting	S
e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. f) Contraction Joints provided or not (CC Pavement) g) Compaction of Flank/slope & raincuts if any 2 Cross Drainage Condition of head walls in Hume pipe Culverts including its painting	
aggregates in case of CC Pavement. f) Contraction Joints provided or not (CC Pavement) g) Compaction of Flank/slope & raincuts if any 2 Cross Drainage Condition of head walls in Hume pipe Culverts including its painting	No
g) Compaction of Flank/slope & raincuts if any 2 Cross Drainage Condition of head walls in Hume pipe Culverts including its painting	
Cross Drainage Condition of head walls in Hume pipe Culverts including its painting	No
a) Condition of head walls in Hume pipe Culverts including its painting	No
painting	
NO CONTRACTOR OF THE PROPERTY	SRI
b) Condition of Abutment & Wing Walls, Slab in RCC Culverts	SRI
c) Condition of railings/slab/approach for Bridges	SRI
3 Raod Furniture	
Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	NO
4 Compliance History	
a) Status of ATR's any others	NO

Overall Rating:

SRI
SKI

NAME:- RAJEEV RANJAN KUMAR DESIGNATION: JUNIOUR ENGINEER Signature 9/12/2