FIELD INSPECTION REPORT

Date of Inspection :	-18-20	District: Combalgrah	
Division: 2 101D=C	sobalgan -)	District: Gobalgan	100
Division: E 007-6	sopagan -1	Length (km): 2,09	_
Name of the Road:	Paharbur Daya	In talathur	
Scheme/Programme:	MAINTENANCE	110 may chair	_
Package No.: MR-H	19-20, GPJ-1/11	Road Id No.:	
Status of the Project:	Ongoing/Completed	/Under Maintenance	_
Work is a case of:	New Connectivity/U	p gradation/ Maintenance	

Sl. No.	l. No. Parameters to be checked		
1.	Payement	Remarks	
a)	Road Junction condition		
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber .		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		
f)	Contraction Joints provided or not (CC Pavement)		
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
-3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		
a)	Status of ATR's & any others	1	

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

7/19/90

2/12/2020

(Signature)

NAME:

DESIGNATION:

work no