FIELD INSPECTION REPORT

		FIELD INSPEC	CTION REPORT	
pate of I	nspection: 3	3.12.20	District: Valle	
Division: Makus			Length (km): 1:10 High level Bec Bridge Word not stored	12 you'sal
Name of	the Road: Ab	Proach Road	High level Rec Briage	ratat BWC
Scheme/	Programme:	MAINTENANCE	Home not stored	
Package			Road Id No.:	
	Status of the Project: Ongoing/Com		eted/Under Maintenance ty/Up gradation/ Maintenance Remar	
Work is a case of:		New Connectivity/U	New Connectivity/Up gradation/ Maintenance	
Sl. No.		Parameters to		A minimum in the
1.	Pavement			S/U
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)				Yes/No
e)	Whether free from defects such as visible crass			Yes/No
	aggregates in case of CC Pavement. Contraction Joints provided or not (CC Pavement)			Yes/No
f)	Contraction Joints provided to			
g)	Compaction of flank/slope & raincuts if any			
2.	Cross Drainage S/SRI/			
a)	Cross Drainage Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab III Ree Condition			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			
3.	Road Furniture Yes/No			
a)	Whether sign boards/informatory/cautionary Board/km & 200m Yes/No stones/Pavement road markings are provided and maintained			
4.	Compliance History			
a)	Status of ATR's & any others			
,				

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

Agreement Done Work not Started.

(Signature)

NAME:

DESIGNATION: कार्यप्रक आभयता ग्रामीण कार्य विभाग कार्य प्रमंडल, महुआ

A. 109