## FIELD INSPECTION REPORT

|                                  | FIELD I  | NSPECTION REPORT                                  |                 |  |
|----------------------------------|--|---|-----------------|--|
| DATE OF INSPECTION:- 10.12.2020. |  | DISTRICT  | SUPAUL          |  |
| DIVISION:- TRIVENIGANI           |  | LENGTH (Km)                                       | 2.655Km.        |  |
|                                  | EOFROAD:- LALPATTI TO  |   |                 |  |
| SCHEME PROGRAMME                 |  | MAINTENANCE                                       |                 |  |
| PACKAGE NO. 13R-35R-83.          |  | Road Id No.:                                      |                 |  |
| STATUS OF PROJECT :              |  | Road Id No.:  ONNGING/COMPLETED/UNDER MAINTENANCE |                 |  |
| Work is a case of:               |  | New Connectivity/ Up gradation/Maintenance        |                 |  |
| Sl.                              | PARAMERER  | RS TO BE CHECKED                                  | REMARK          |  |
| No.                              | PAVEMENT   |   | √s/U            |  |
| a                                | Road junction condition  |   | ✓ S/U           |  |
| b                                | Condition of Surface   |   |                 |  |
| С                                | Riding Quality   |   |                 |  |
|                                  | Road Camber  |   |                 |  |
| e                                | Whether free fron defectssuch as visible cracks exposed aggregates in case of CC pavement                            |   |                 |  |
| f                                | Construction Joints provided or not (CC Pavement)  |   |                 |  |
| g                                | Compaction of flank/ Slope & Rain cuts if any  |   |                 |  |
| 2                                | Cross Drainage   |   | S/SRI/U         |  |
| а                                | Condition of head walls in Hume pipe culverts including its painting   |   |                 |  |
| b                                | Condition of abutment & Wing walls, Slab in RCC culverts   |   |                 |  |
| С                                | Condition of railings/slab/approach for Bridges  S/SRI/U   |   |                 |  |
|                                  | n I Frankura   |   |                 |  |
| -                                | Whether sign boards/informatory/cautionary Board/km & 200m stones/ Pavment road markings are provided and maintained |   |                 |  |
|                                  | Compliance History   |   | Yes/No N        |  |
|                                  | Status of ATR's & any Others   |   | 163/1101        |  |
|                                  | 6  | Satisfactory (S)                                  | S'              |  |
| Overall Rating :                 |  | Satisfactory but requi                            | res Improvement |  |
|                                  |  | Unsatisfactory (U)                                |                 |  |

10/10/10 De 2/10

(VIKAS KUMAR SAH)

Signature<sup>20</sup>