

FIELD INSPECTION REPORT

Inspection : 10.12.2020	District: Samastipur
Location: Patoni	Length (km): 1.210 km.
of the Road: Mukhya Sadak to Mahadeli Tola	
Programme: MAINTENANCE	MM4SY (SC)
Project No.:	Road Id No.:
of the Project: Ongoing/Completed/Under Maintenance ✓	
in a case of: New Connectivity/Up gradation/ Maintenance	

Parameters to be checked	Remarks
Pavement	
Road Junction condition	✓ S/U
Condition of Surfacing	✓ S/U
Riding Quality	✓ S/U
Road Camber	✓ S/U
Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
Contraction Joints provided or not (CC Pavement)	✓ Yes/No
Compaction of flank/slope & raincuts if any	✓ Yes/No
Cross Drainage	
Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
Condition of railings/slab/approach for Bridges	S/SRI/U
Road Furniture	
Whether sign boards/informatory/cautionary Board/km & 200m ones/Pavement road markings are provided and maintained	✓ Yes/No
Compliance History	
Status of ATR's & any others	

ing

:

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Arjun Kumar
10.12.2020
(Signature)

Arbind Kumar Jha.

ON: AE, PWD, Subdiv - Vidya Pati Nagar
Samastipur