## FIELD INSPECTION REPORT

1	FIELD INSPECT		
Mai	te of Inspection: 10 · 12.2020	District: Samastipur	
	vision: RWD Dalsinghsarai	Length(km): 3.500 km	
Nan	ne of Road: Rai fur Bazar to Balbha	dar pur meshi	
		NP 2018 Road Id No:	
Pacl	kage No: us of the Project: Ongoing/Completed/Under Main		
	rk is a case of:  New Connectivity/ Up gradat	ion/ Maintenance - w	gradation
Wor SI. No	Parameters to be Check		Remarks
10	Pavement		
1)	Road Junction Condition		
)	Condition of Surfacing		
:)	Riding Quality		
)	Road Camber		
)	Whether free from defects such as visible cracks, aggregates in case of CC Pavement		
)	Constraction Joint provided or not(CC Pavement)		
()	Compaction of flank/slope & raincuts if any		
,	Cross Drainage		
)	Condition of head walls in Hume pipe culverts including its painting		
) )	Condition of Abutment & Wing walls, Slab in Re		
	Condition of railings/slab/approach for Bridge		
)	Road Furniture		
)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Main bow Fixed
	Compliance History		<u></u>
	Status of ATR's & any others		MO
<i>†i</i>	Pulated date of Completion 11.5 1 Overall Rating:	9.11.2020 Sut till	Now pot Sentaen Not Stand.
	Satisfactory(S)	(05.7)	20-
	Satisfactory but requires Imp	provement(SRI)	SPI
	Unsatisfactory(U)		

(Signature)

NAME: **DESIGNATION:**