## FIELD INSPECTION REPORT

112/2020	District: Munger
1_	Length (km): 1-200
01 to chadaun	
MAINTENANCE	New maintenance
1/2	Road Id No.: 537
Ongoing/Completed	Under Maintenance
New Connectivity/L	Jp gradation/ Maintenance
	Ongoing/Completed

Sl. No.	Parameters to be checked	Remarks	10
1.	Payement	THE RESERVE	
a)	Road Junction condition	<i>⊸</i> 8/U	
b)	Condition of Surfacing	<b>-8/U</b>	
c)	Riding Quality	∪S/U	
d)	Road Camber	US/U	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	H
ſ)	Contraction Joints provided or not (CC Pavement)	Yes/No	וע
g)	Compaction of flank/slope & raincuts if any	· Yes/No	N
2.	Cross Drainuge		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	)
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	74
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture	20世 1986	
a) -	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
14.	Compliance History	Claring a	
a)	Status of ATR's & any others	NO	

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

(Signature)

fam Dazes Joh NAME: Executive Eximes\_ scanued with Campage 12-03-2020 08:58 12-03-2020 08:58 17-03-2020 08:58 17-03-2020 08:58