## FIELD INSPECTION REPORT

Date of Inspection: 8/12/2020  Division: Buisi		District: Purnea Length (km): 2.500 km	
Scheme/Programme:	MAINTENANCE	IMR goral	
Package No.:		Road Id No.:	
Status of the Project:	Qngoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
	The same of the sa	The same of the sa	

SI. No.	Parameters to be checked Re				
i.	Pavement				
a)	Road Junction condition	S/U-NA			
b)	Condition of Surfacing	S/U-NA			
c)	Riding Quality	S/U_HA			
d)	Road Camber	S/U_ HA			
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No HA			
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N			
g)	Compaction of flank/slope & raincuts if any	Yes/No			
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting				
b)	b) Condition of Abutment & Wing walls, Slab in RCC culverts c) Condition of railings/slab/approach for Bridges				
c)					
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4.	Compliance History				
a	CATDLE Bank albare	No			

Overall Rating

1	Satisfactory (S)	-MA-		
	Satisfactory but requires Improvement (SRI)	nalb	ren Stel	rel)
	Unsatisfactory (U)			ا

NAME: GIAURAY KUMAA
DESIGNATION: PHISTAHT ENGINEER