

FIFTH INSPECTION REPORT

Date of Inspection: 6/12/2020 District: MUZ.
 Division: R.W.D MUZ east-1 Length (km): 3.8 km
 Name of the Road: In Mahaur Ram house (Bakhor) to
 Scheme Programme: MAINTENANCE Balthana polchor via Adam chhar
 Package No.: Road Id No.:
 Status of the Project: Ongoing Completed Under Maintenance
 Work is a case of: New Connectivity Up gradation Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S U
b)	Condition of Surfacing	S U
c)	Riding Quality	S U
d)	Road Camber	S U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes No
f)	Connection joints provided or not (CC Pavement)	Yes No
g)	Compaction of bank slope & talments if any	Yes No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its paring	S SRI U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S SRI U
c)	Condition of railings slab approach for Bridges	S SRI U
3.	Road Furniture	
a)	Whether sign boards informative cautionary Board km & 200m stones Pavement road markings are provided and maintained	Yes No
4.	Compliance History	
a)	Status of ATR's & any others	

Not started

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

[Signature]
 6/12/2020
 (Signature)

NAME:

DESIGNATION: