

# FIELD INSPECTION REPORT

Date of Inspection :	7/12/2020	District:	East Champaran, Motihari
Division :	Works division Pakhailaya	Length (km):	0.950 km
Name of the Road:	Betauna Hanuman mandir To Parti + 0.9		
Scheme/Programme:	MAINTENANCE	New Maintenance - 2018	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

No.	Parameters to be checked	Remarks
<b>Pavement</b>		
1)	Road Junction condition	S/U NA
2)	Condition of Surfacing	S/U NA
3)	Riding Quality	S/U NA
4)	Road Camber	S/U NA
5)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
6)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
7)	Compaction of flank/slope & raincuts if any	Yes/No
<b>Gross Drainage</b>		
1)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
2)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
3)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
<b>Road Furniture</b>		
1)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Sign Board/Yes/No Informatory B.L.
<b>Compliance History</b>		
1)	Status of ATR's & any others	NA

Overall Rating :	Satisfactory (S)	'S'
	Satisfactory but requires Improvement (SRI)	
	Unsatisfactory (U)	

Work in Progress  
 S. A. S.  
 7/12/2020  
 RE

(Signature)