FIELD INSPECTION REPORT

Date of Inspection: 04/12/2020	District: Samastipur
Division: RWD Dalsinghsarai	Length(km): 1.650
Name of Road :Repair of road from Deni chow	k to se Bhartiya state bank dalsingsari tak
Scheme / Programme: MAINTENANCE	
Package No:-RM/SA/DAL/19/12	Road Id No: –
Status of the Project: Ongoing	
Work is a case of: New Connectivity/ Up	gradation/ Maintenance
Sl. No Parameters to be	Checked Remark
1 Pavement	
Road Junction Condition	"S"
Condition of Surfacing	"S"
Riding Quality	"S"
Road Camber	"S"
Whether free from defects such as visible of aggregates in case of CC Pavement	eracks, exposed NO
Construction Joint provided or not(CC Pave	ement) NO
Compaction of flank/slope & raincuts if any	y _
Cross Drainage	
Condition of head walls in Hume pipe culve including its painting	erts "S"
Condition of Abutment & Wing walls, Slat	o in RCC culverts
Condition of railings/slab/approach for Brid	
Road Furniture	
Whether sign boards/information/cautionary stones/Pavement road markings are provided	y Board/km & 200m d and maintained YES
Compliance History	
Status of ATR's & any others	NO

Overall Rating :

· "SRI"
SICI

Patchport work has been completed by agency as per direction on due time surface work has been not completed due to slum of drain beside road & road also at present due to onway traffic in market area surface work of road is in completed.

NAME:

Deepak Chandra Sinha Junior Engineer

DESIGNATION: