


FIELD INSPECTION REPORT

Date of Inspection : 11-12-2020		District : Mangalore	
Division : Mangalore		Length (km):	
Name of the Road: PAMPA NH 28 to Panathur			
Scheme/Programme: MAINTENANCE		Road Id No.:	
Package No.:		Ongoing/Completed/Under Maintenance	
Status of the Project:		New Connectivity/Up gradation/ Maintenance	
Work is a case of:		Parameters to be checked	
Sl. No.		Remarks	
1. Pavement		S/U N/A	
a) Road Junction condition		S/U N/A	
b) Condition of Surfacing		S/U	
c) Riding Quality		S/U	
d) Road Camber		Yes/No	
e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No	
f) Contraction Joints provided or not (CC Pavement)		Yes/No	
g) Compaction of flank/slope & raincuts if any		Yes/No	
2. Cross Drainage		S/SR/U	
a) Condition of head walls in Hume pipe culverts including its painting		S/SR/U	
b) Condition of Abutment & Wing walls, Slab in RCC culverts		S/SR/U	
c) Condition of railings/slab/approach for Bridges		S/SR/U	
3. Road Furniture		Yes/No	
a) Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No	
4. Compliance History			
a) Status of ATR's & any others			
Overall Rating : Just below work stand alone road			
Satisfactory (S)			
Satisfactory but requires Improvement (SRI)			
Unsatisfactory (U)			


 11/12/20
 (Signature)

NAME: Bandhanth Desai
 DESIGNATION: PE, Mangalore