FIELD INSPECTION REPORT

Date ofo Inspection: 11 12 2020					District : GAYA	
Divison: Neemchak Bathani					Length (Km.: 0.894	
Scheme/Programme: MAINTENANCE Lo 51-ma					-mompur Teusa Rd	Tol to
Pack	age No.: 🐬	AN E		Road Id No.: NA		
Status of the Project :			Ongoing/Co	Ongoing/Completed/Under Maintenance		
Work is a case of :				New Connectivity/Up gradation/Maintenance		
Sl. No.			Parameters to			Remarks
1	Pavement					
8)	Road Junction condition					L-870
b)	Condition of	Surfacing				S/U_
c)	Riding Quali	ty				S/U_
d)	f) Road Camber					18/U
e)	e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.					Yes/No
f)						Yes/No
g)	Compaction of flank/slope & raincuts if any					Yes/No
2	Cross Drain	nage				
a)	Condition of head walls in Hume pipe culverts including its painting					S/SRI/U
b)	b) Condition of Abutment & Wing walls, Slab in RCC culverts					S/SRI/U
c)	Condition of railings/slab/approach for Bridges					S/SRI/U
3	Road Furniture					
2)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained					
4	Compliance History					
a)	Status of AT	R's & any others.				
Ove	rall Rating	:				
		Satisfactory (S)				
		Satisfactory but requi	res Improvement (SRI)		
		Unsatisfactory (U)				**

U

