FIELD INSPECTION REPORT

| | ate ofo Inspection : | District | : GAYA | |
|---|---|------------------------------------|----------------|----------|
| Divison: Neemchak Bathani; Sub Division - Manpur Length (Km.: 1.768 K | | | Km.: 1.768 Km. | |
| Sch | cheme/Programme: NABARD MAINTENANCE Graya-Fatehpur Road to Bandhua | | | |
| | Package No.: N/A Road Id No.: N/A | | | |
| Stal | tus of the Project: Under Maintenance | Ongoing/Completed/Under Maintena | nce | |
| Wo | ork is a case of: Maintenance | New Connectivity/Up gradation/Main | ntenance | |
| SI. No. | Parameters to be checked | | Remarks | |
| 1 | Pavement | Management of the | | The same |
| a) | Road Junction condition S S/ | | | S/U |
| b) | Condition of Surfacing U | | S/U | |
| c) | Riding Quality U | | U | S/U |
| d) | Road Camber | | S | S/U |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | Yes/No | |
| f) | Contraction Joints provided or not (CC Pavement) N/A | | Yes/No | |
| 2) | Compaction of flank/slope & raincuts if any | | Yes/No | |
| 2 | Cross Drainage | | | |
| 1) | Condition of head walls in Hume pipe culverts including its painting | | S | S/SRI/U |
|) | Condition of Abutment & Wing walls, Slab in RCC culverts | | N/A | S/SRI/U |
|) | Condition of railings/slab/approach for Bridges | | N/A | S/SRI/U |
| | Road Furniture | | | |
| | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and yes/No maintained | | | |
| W 3 | | | | |
| 1 | Compliance History Status of ATR's & any others. No ATR. | Flank (Both Side) Require | es Improvement | |

Overall Rating

| Satisfactory (S) | |
|---|------|
| Satisfactory but requires Improvement (SRI) | SRI. |
| Unsatisfactory (U) | |

J11/12/2020. A.E.R.W.D. Manpur.