


# FIELD INSPECTION REPORT

|                        |                                            |              |        |
|------------------------|--------------------------------------------|--------------|--------|
| Date of Inspection :   | 12.12.2020                                 | District:    | Purnea |
| Division :             | Baisi                                      | Length (km): | 5.0 km |
| Name of the Road:      | TOL (satbita) to Pargurua                  |              |        |
| Scheme/Programme:      | MAINTENANCE                                |              |        |
| Package No.:           |                                            | Road Id No.: |        |
| Status of the Project: | Ongoing/Completed/Under Maintenance        |              |        |
| Work is a case of:     | New Connectivity/Up gradation/ Maintenance |              |        |

| Sl. No. | Parameters to be checked                                                                                             | Remarks    |
|---------|----------------------------------------------------------------------------------------------------------------------|------------|
| 1.      | <b>Pavement</b>                                                                                                      |            |
| a)      | Road Junction condition                                                                                              | S/U NA     |
| b)      | Condition of Surfacing                                                                                               | S/U NA     |
| c)      | Riding Quality                                                                                                       | S/U NA     |
| d)      | Road Camber                                                                                                          | S/U NA     |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No NA  |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No NA  |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | Yes/No NA  |
| 2.      | <b>Cross Drainage</b>                                                                                                |            |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U NA |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U NA |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U NA |
| 3.      | <b>Road Furniture</b>                                                                                                |            |
| a)      | Whether sign boards/informatory/cautionary Board km & 200m stones/Pavement road markings are provided and maintained | Yes/No NA  |
| 4.      | <b>Compliance History</b>                                                                                            |            |
| a)      | Status of ATR's & any others                                                                                         | NA         |

Overall Rating :

|                                             |    |
|---------------------------------------------|----|
| Satisfactory (S)                            | NA |
| Satisfactory but requires Improvement (SRI) |    |
| Unsatisfactory (U)                          |    |

  
 12/12/2020  
 (Signature)  
 A.B. Barua

NAME:  
 Ashim Kumar