

FIELD INSPECTION REPORT

Date of Inspection :- 11/12/2020	District :- Buxar
Division :- Buxar	Length (km): 16.00 km
Name of the Road:- NH-84 Buxar Golambei Se Damraon via Jaso, Naddan Kulharia Surrounding Path	
Scheme/Programme: MAINTENANCE	
Package No.: MR-N/19-20 Buxar / 17	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

S. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No/ N.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No/ N.A
g)	Compaction of flank/slope & raincuts if any	Yes/No ✓
	Cross Drainage	
	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U/ N.A
	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U/ N.A
	Condition of railings/slab/approach for Bridges	S/SRI/U/ N.A
	Road Furniture	
	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained 200m	Yes/No ✓
	Compliance History	
	Status of ATR's & any others	NO.

Overall Rating :

Satisfactory (S) ✓	3
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

[Signature]
(Signature) 11.12.20



REDMI NOTE 6 PRO
MI DUAL CAMERA