

FIELD INSPECTION REPORT

Date of Inspection :- 11/12/2020		District:	Buxar
Division :- Buxar		Length (km):	0.30 Km
Name of the Road:- Buxar chausa p.w.D. Path se Hawai adda Path.			
Scheme/Programme:		MAINTENANCE	
Package No.:		Road Id No.:	
Status of the Project:		Ongoing/Completed/Under Maintenance ✓ under maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		✓S/U
b)	Condition of Surfacing		✓S/U
c)	Riding Quality		✓S/U
d)	Road Camber		✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)		✓Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No ✓
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U N.A.
c)	Condition of railings/slab/approach for Bridges		S/SRI/U / N.A.
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		✓Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		ND

Overall Rating :

Satisfactory (S) ✓		'S'
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

NAME:



REDMI NOTE 6 PRO
MI DUAL CAMERA

(Signature) 11.12.20