

FIELD INSPECTION REPORT

Date of Inspection : 11.12.2020		District: Darbhanga.
Division : RWD W(DW) Darbhanga-2		Length (km): 1.220 KM.
Name of the Road: PWD to Areya Madhup.		
Scheme/Programme: MAINTENANCE		MMGSY.
Package No.:		Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Upgradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	-S/U NA
c)	Riding Quality	-S/U NA
d)	Road Camber	-S/U NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank/slope & raincuts if any	-Yes/No ✓
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	-S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	-S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	—

NAME: Kumar Chandraj.
DESIGNATION: Asst. Engineer.

कुमार चन्द्रज
11.12.2020
(Signature)
सहायक अभियन्ता
ग्रामीण कार्य विभाग
कार्य अवर प्रमंडल, सिंहबाड़ा

* वर्ष 2020 में आगी बवंडर बाढ़ के कारण पथ के कई पंचाशों पे surface damage एवं Rain cuts हो गया है।