FIELD INSPECTION REPORT

Date of Inspection:).	2-12-2020	District: Nawada		
Division: Raso	nuli	Length (km): 1.60 (C-M)		
Name of the Road: LU52-Karanpura poth To BISHUM GOMS				
Scheme/Programme:	MAINTENANCE			
Package No.: 8 P				
Status of the Project:	Ongoing/Completed/Under Maintenance			
Work is a case of:	New Connectivity/Up gradation/ Maintenance			

SI. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	š/U	
b)	Condition of Surfacing	š/U	
c)	Riding Quality	\$/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
Ŋ	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
Ž	Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.2.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
J Esti	Compliance History		
N. S.	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	2
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	_

(Signature)

NAME: SHALEN SINHA

DESIGNATION: JE ROH

MA