"out of maintened

FIELD INSPECTION REPORT

Date of I	nspection:	12/12/2020	District:		
Division: 79MW			7940		
Name of	the Road: B	aluadin to mo	Length (km): 7075k	H	
Scheme/	Programme:	MAINTENANCE	TOUR FOR IN JAME	dist	
Package	No.:	**************************************	Road Id No.: 208041	0810-	
	the Project:	Ongoing/Complete	Completed/Under Maintenance		
Work is a case of:		New Connectivity/	Up gradation/ Maintenance		
SINO		is the other was a second		Remarks	
k in	Pavement 2				
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
"Mait	(ខេត្តប្រែក្រព្រះ				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
	eko a saraju	ĥ			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
為別的	recomplinical tribal for the property of the p			\$\$ \$P.C.\$\$	
a) Status of ATR's & any others					
Overall Rating : [S. 45 - 45 - 15]				N.A.	
Overall	Rating :	Satisfactory (S)			
	8	A STATE OF THE PARTY OF THE PAR	equires Improvement (SRI)		
	E	Unsatisfactory (U)	* *	

(Signature)

NAME:

DESIGNATION: