## FIELD INSPECTION REPORT

Date of Inspection: 12/12/2020			District: James		
Division: James			Length (km): 3. 175 km		
Name of	The second of th	mut kamalcol	Road (Cropalpyo) to Han	iadih	
	Programme:	MAINTENANCE	, ,		
Package			Road Id No.: 2080410	8156	
			pleted/Under Maintenance		
			w Connectivity/Up gradation/ Maintenance		
SICNO			o be coecked	Remarks	
	Na Winding			1.57.30	
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/Ú	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of	Yes/No			
李斯	ing policy in the party of	<b>网络尼山</b>			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
ek. At		ire			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
<b>华</b> 斯.洲 <b>·</b>	ង៥៤០៣ឮប្រព័ត្	miore de la company	型的 <b>对。[1] 44 (1) 19 (1) 4</b> (4)	# 1948 ##	
a)	Status of AT	R's & any others			

**Overall Rating** 

	10 11
Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	· ·

(Signature)

NAME:

**DESIGNATION:**