

FIELD INSPECTION REPORT

Date of Inspection: 2.12.2020		District: Samastipur	
Division: RWD Dalsinghsarai		Length(km): 0.915 km.	
Name of Road : NH 103 Se Gussana purv hote sirya kanson prachand mdp jale			
Scheme / Programme: MAINTENANCE		old m/r	
Package No:		Road Id No:	
Status of the Project: Ongoing/Completed/Under Maintenance - Beyond Maint.			
Work is a case of:		New Connectivity/ Up gradation/ Maintenance	
Sl. No	Parameters to be Checked		Remarks
1	Pavement		
a)	Road Junction Condition	5 years Maint period is Over on 02/12/2020.	
b)	Condition of Surfacing	Surface is in good condition.	
c)	Riding Quality		
d)	Road Camber		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		
f)	Constraction Joint provided or not(CC Pavement)		
g)	Compaction of flank/slope & raincuts if any		
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of Abutment & Wing walls , Slab in RCC culverts		
c)	Condition of railings/slab/approach for Bridge		
3	Road Furniture		
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory(S)	5
Satisfactory but requires Improvement(SRI)	-
Unsatisfactory(U)	-


 12/12/2020
 (Signature)

NAME:

DESIGNATION :

Anil prasad
 OR