FIELD INSPECTION REPORT

| Date of I | nspection: 13 | 12/2020 | District: East champaran | |
|--------------------------------------|--|---|--|--------------|
| Division: Frence Length (km): 2,149 | | | | |
| | the Road: Tol | Saraya Baran | Tola-to Kishori Tola. | 100 |
| | | MAINTENANCE | | |
| Package No.: AR-11R-665 Road Id No.: | | | | |
| _ | | Ongoing/Completed/Under Maintenance | | |
| Work is a case of: | | New Connectivity/Up gradation/ Maintehance Parameters to be checked Remarks | | |
| SI. No. | | Parameters to | Be checked | Remarks |
| 1. | Pavement | | Angara Bungar Mangalan Pelanggan Mangalan Pelanggan Mangalan Pelanggan Bangaran | uranida sara |
| a) | Road Junction condition | | | S/JJ |
| b) | Condition of Surfacing | | | S/U |
| c) | Riding Quality | | | S/JJ |
| d) | Road Camber | | | S/Ų⁄ |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | | Yes/No |
| f) | Contraction Joints provided or not (CC Pavement) | | | Yes/No |
| g) | Compaction of flank/slope & raincuts if any | | | Yes/No . |
| 2. | Cross Drainage | | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | | | S/\$RI/U |
| b) · | Condition of Abutment & Wing walls, Slab in RCC culverts | | | S/\$RI/U |
| . c) | Condition of railings/slab/approach for Bridges | | | S/SRI/U |
| 3. | Road Furnitu | r c | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | | |
| 4. | Compliance History | | | |
| a) | Status of ATR' | s & any others | | No |

Overall Rating

| Satisfactory (S) | 9 |
|---|---|
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

(Signature)

NAME: Hendonson

DESIGNATION: 15- , RWD. 1600009

Scanned with CamScanner