

FIELD INSPECTION REPORT

Date of Inspection :	14.12.2020	District:	West Champaran
Division :	Bagaha-2	Length (km):	1.60
Name of the Road:	Koiri tola to Bagasahi (VR29)		
Scheme/Programme:	MAINTENANCE		
Package No.:	BR-37R-570	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A
f)	Contraction Joints provided or not (CC Pavement)	N/A
g)	Compaction of flank/slope & raincuts if any	N/A
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S (yes)
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	yes
c)	Condition of railings/slab/approach for Bridges	N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	yes
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Nagendra Kumar
(Signature)

NAME: Nagendra Kumar

DESIGNATION: JE