

FIELD INSPECTION REPORT

| Date of Inspection: | 10.12.2020 | District: | Madhubani |
|---|---|-------------|-----------|
| Division: | Benipatti | Length(Km): | 0.750 km |
| Name of Road: | Changuli Mahadulit up house Shale Rai to Changuli Sahipatti Sakur das kuter | | |
| Scheme/Programme: | Maintenance | | |
| Package No. | | Road Id No. | |
| Status of the Project: | Ongoing/Completed/ Under Maintenance | | |
| Work is a case of: | New Connectivity/Up gradation/ Maintenance | | |
| S No. | Parameters to be Checked | Remarks | |
| 1 | Pavement | | |
| a) | Road Junction condition | S/U | |
| b) | Condition of Surfacing | S/U | |
| c) | Riding Quality | S/U | |
| d) | Road Camber | S/U | |
| e) | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement | Yes/No | |
| f) | Contraction Joints provided or not (CC Pavement) | Yes/No | |
| g) | Compaction of flank /slope & raincuts if any | Yes/No | |
| 2 | Cross Drainage | | |
| a) | Condition of head walls in Hume pipe culverts including its painting | S/SRI/U | |
| b) | Condition of Abutment & Wing walls, Slabs in RCC culverts | S/SRI/U | |
| c) | Condition of railing /slabs/ approach for Bridges | S/SRI/U | |
| 3 | Road Furniture | | |
| a) | Whether sign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained | Yes/No | |
| 3 | Compliance History | | |
| a) | Status of ATR's & any others | | |
| Overall Rating: | | | |
| Satisfactory (S) | | | |
| Satisfactory but requires Improvement (SRI) | | SRI | |
| Unsatisfactory (U) | | | |

Name: Ravi nayam prasad singh
Designation: S.E R.W.D Durbhanga circle

(Signature)

12/12/2020

Scanned by CamScanner

Scanned by CamScanner