

FIELD INSPECTION REPORT

Date of Inspection :	4/12/20	District:	Madhepura
Division :	Madhepura	Length (km):	7.025
Name of the Road:	Sahugarda Birani-Habampur		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	M/A S/U
b)	Condition of Surfacing	u S/U
c)	Riding Quality	y S/U
d)	Road Camber	b S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	y Yes/No
f)	Contraction Joints provided or not (CC Pavement)	u Yes/No
g)	Compaction of flank/slope & raincuts if any	u Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	u S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	y S/SRI/U
c)	Condition of railings/slab/approach for Bridges	u S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	y Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	M/A
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Birendra Kumar
04/12/20
NAME: J.E

Birendra Kumar
(Signature) J.E