FIELD INSPECTION REPORT

Da	nte of Inspection:) (1.12.2020	District: Sa	mastinur	
Di	vision: RWD Dalsing	hsarai	District: Samastipur Length(km): 1,270/Cu From madya Widaylya Uziyarpurse munical matho k		in the second
Na	Name of Road: Repair of Road From mady a Widaylya Vizigar Dur se munical matho				
Scheme / Programme: MAINTENANCE NEW MIR-2018 hote hie wingowhy state					
Package No:					
Sta	tus of the Project: On	going/Completed/Under	r Maintenance	en gainy	
WC	ork is a case of:	New Connectivity/ Up	gradation/ Mainten	ance upga	dation
SI. No	Parameters to be Checked Remarks				
1_	Pavement				
a)	Road Junction Con-				
b)	Condition of Surfacing				
c)	Riding Quality				
d)	Road Camber				
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement				
f)	Construction Joint provided or not(CC Pavement)				
g)	Compaction of flank/slope & raincuts if any				
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting				
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				
c)	Condition of railings/slab/approach for Bridge				
3	Road Furniture				
1)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
1	Compliance History				
1)	Status of ATR's & any others				
Overall Rating:					
Satisfactory(S)					
		Satisfactory but requires Improvement(SRI)			SPI
	Ĺ	Unsatisfactory(U)			

14 72/202 (Signa, 10)

NAME: NAME: DESIGNATION:

ov