## FIELD INSPECTION REPORT

	TILLED INDI BOT	101111		The second secon	
Date of Inspection: 12, 12 - 2020		District: Samastipur			
Division: RWD Dalsinghsarai Length(km):			2-5		
Name of Road: Alampur dit, Birendar Stoyh house to Alambur Kothi					
Scheme/Programme: MAINTENANCE MR/ ald					
Package No:  Road Id No:					
Status of the Project: Ongoing/Completed/Under Maintenance and Beyond maintener					
Work is a case of: New Connectivity/ Up gradation/ Maintenance					
SI. No	Parameters to be Checked			Rema as	
1	Pavement				
a)	Road Junction Condition		resource are as		
b)	Condition of Surfacing	1 of The	Year Maint.		
c)	Riding Quality		The or	and was completion	
d)	Road Camber		00 16	03/2013,	
c)	Whether free from defects such as visible cracks, eaggregates in case of CC Pavement	At po	esent werk was		
f)	Construction Joint provided or not(CC Pavement)		avard	W in New MRZOR	
ဋ္ဌ)	Compaction of flank/slope & raincuts if any				
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting				
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				
c)	Condition of railings/slab/approach for Bridge				
3	Road Furniture				
a)	Whether sign boards/information/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4	Compliance History				
a)	Status of ATR's & any others				
	Degood Maint. No poinsion of syeon Haint. Work Somehund Overall Rating: in New HR,				
	Satisfactory(S)				
	Satisfactory but requires Improvement(SRI)				
	Unsatisfactory(U)			<b>!</b>	

12 12 xa (Signature)

NAME: Mananyay Yumar DESIGNATION: AR