FIELD INSPECTION REPORT

	TILLD INSI LCI	101110			
			District: Samastipur		
	sion: RWD Dalsinghsarai	Length(km): 9500K			
Name of Road: NH28 se basanya se seventing Toole.					
Scheme / Programme: MAINTENANCE - old MIR					
Package No: Road			oad Id No:		
Status of the Project: Ongoing/Completed/Under Maintenance					
Work is a case of: New Connectivity/ Up gradation/ Maintenance Beyood Mount.					
SI. No	Parameters to be Checked Remarks			Rema iss	
1	Pavement				
a)	Road Junction Condition	Ro	nd town	ferren to	
b)	Condition of Surfacing	R	(e1)		
c)	Riding Quality				
d)	Road Camber				
(د)	Whether free from defects such as visible cracks, e aggregates in case of CC Pavement	kposed			
t)	Construction Joint provided or not(CC Pavement)				
g)	Compaction of flank/slope & raincuts if any				
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting				
b)	Condition of Abutment & Wing walls, Slab in RCC culverts				
c)	Condition of railings/slab/approach for Bridge				
3	Road Furniture				
a)	Whether sign boards/information/eautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4	Compliance History				
a)	Status of ATR's & any others				
	Overall Rating : Satisfactory(S) Satisfactory but requires Impr	ovement(SRI)		_NA-	
	Unsatisfactory(U)				

william row

(Signa, ac)

NAME: Day Kishere Thatus

DESIGNATION: E