FIELD INSPECTION REPORT

Date of Inspection: 11-12-2020			District: Awahashad	
Division: Daldhagor			District: Awangebod Length (km): 7.50 km	- 6
	the Road:	Aganda to p	chidah	
Property Character	Programme:	MAINTENANCE		
Package No.:			Road Id No.:	
The state of the s			d/Under Maintenance	
14.30	a case of:	New Connectivity	/Up gradation/ Maintenance	
Sl. No.		Parameters t	o be checked	Remarks
1.	Pavement			
a)	Road Junction condition			SAU
h)	Condition of Surfacing			s/y
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Draina	ge		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furnite	ire		
a)	The state of the s		y/cautionary Board/km & 200m re provided and maintained	Yes/No

stones/Pavement road markings are provided and maintained

Overall Rating

a)

Compliance History

Status of ATR's & any others

22100	Satisfactory (S)	
200000	Satisfactory but requires Improvement (SRI)	
No. of Control	Unsatisfactory (U)	V

(Signature)

NAME: Shubhan too DESIGNATION: J.F.