## FIELD INSPECTION REPORT

oivision : Same of		12/2020	District: Banka- &	
ame of	1241129		Length (km): 19.307-	
	the Road: Su	vya - Bhelu MAINTENAN	a road to Pulwara.	
				1. 6
ackage	No.: M the Project:	R (old)	Road Id No.: 207036068 pleted/Under Maintenance	45.
	a case of:		vity/Up gradation/ Maintenance	***************************************
1. No.				Remarks
1.	Pavement			
a)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
(c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			Ś/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)	Status of ATR's & any others			
Overall	Rating :	200		
Satisfact		Satisfactor		
		Satisfactory Unsatisfact	y but requires Improvement (SRI)	

NAME: Krishna Kr. Sinha.

DESIGNATION: Executive Engineer RWD. Banka-2.