## FIELD INSPECTION REPORT

Date of Inspection: 8/12/2020 District: Banka							
Division: Banka - 2			Length (km): 3.95 Km				
Name of	the Road: An	nuwa Longaly	to Adhisa Willage (Under NM	P-2018)			
	2 rogramme.	I WHITE TENANCE					
The state of the s	No.: RM/BA/E	3AN/20/ 0011	Road Id No.: 2070 350 103	7			
	a case of:	AND DESCRIPTION OF THE PROPERTY OF THE PROPERT	ted/Under Maintenance y/Up gradation/ Maintenance				
Sl. No.		CONSTRUCTOR - CARROLLAND	to be checked	Remarks			
1,	Pavement						
a)	Road Junction	n condition	S/U				
b)	Condition of	Surfacing	S/U				
c)	Riding Quality				On hoing, only pot patch wom work is in		
d)	Road Camber S						
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.						
f)	Contraction J	oints provided or n	Yes/No	Progress			
g)	Compaction of flank/slope & raincuts if any						
2.	Cross Drains						
a)	Condition of	head walls in Hum	S/SRI/U	ongoing			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	N/A B		
c)	Condition of railings/slab/approach for Bridges S/				N/A On Going		
3.	Road Furniture						
a)	Whether signstones/Paven						
4.	Compliance						
a)	Status of ATI	R's & any others		N/A			

Overall Rating

Satisfactory (S)	`S!
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signallité)020

NAME: Korshna Kumar Sinha

DESIGNATION: EEIRWD

Banka-2