## FIELD INSPECTION REPORT

	_			
Date of	of Inspection: 14/12/2020 District: Nalandy			
Division: Shankland			Length (km): 1-700 K·M·	
Name	r the Roull:	SFH2 7	o Kushaz.	
Schem	Programme: MA	INTENANCE	NABARD.	
Packag			Road Id No.:	
Status	of the Project: Ong	going/Completed	Under Maintenance	
	s a case of: Nev	v Connectivity/U	p gradation/ Maintenance	
Sl. No.	Parameters to be checked			Remarks
1.	Pavement			in it is
ล)	Road Junction condition			S/U
b)	Condition of Surfacing			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
<b>2.</b> (2)	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3.	Road Furniture			Si Si Ciri
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
4.	Compliance History			
a)	Status of ATR's & any others			-NO-

**Overall Rating** 

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

\* Road Camage in Flood 2019. Restorotion estimate Submitted.

NAME: Mukesh Yaday DESIGNATION: J.E.

Scanned with CamScanner