## FIELD INSPECTION REPORT

	Inspection: 12	1/12/2020	District: Nalanda		
Divisio		sharif	Length (km): 0 0000 1:0	OOKM	
	of the Road: N	482 POWER +	rouse being painted no	al Nato	io Luy!
Scheme	c/Programme:	MAINTENANCE	Hens-45 PS MAP	BL	inyad
Packag	- 110		Road Id No.:		J
Status of the Project: Ongoing/Completed/Under Maintenance Work is a case of: New Connectivity/Un production/ Additional Connectivity/Un production/ Additional Connectivity/University (Connectivity/University)		/Under Maintenance			
		New Connectivity/U	Jp gradation/ Maintenance		
Sl. No.	Parameters to be checked			Remarks	
.1.	Pavement				1
a)	Road Junction condition			S/U O	1
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	NA
d)	Road Camber			S/U .	1/27
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No	1 1
f) ·	Contraction Joints provided or not (CC Pavement)			Yes/No	$\exists$
g)	Compaction of flank/slope & raincuts if any			Yes/No	1/ M
2.	Cross Drainage				4
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U				7
b)	Condition of Abutment & Wing walls, Slab in RCC culverts  S/SRI/U				1
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	-/ HD
3.	Road Furniture				1
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	N (
4.	Compliance H	listory	· · · · · · · · · · · · · · · · · · ·	The Land	1
a)	Status of ATR's & any others			1	0.0

Overall Rating Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

प्रम के एउँ है एउत्पक्ष सातमिङ्चय यीजनार्वजात् नल जल दार्य का प्रम किलागारामा है जिसके आरण का क्याबुर्व है (Signature)4/14 120

NAME: Mukes Yordow DESIGNATION: J. E.

Scanned with CamScanner